



Safety Performance 2007

Maersk Oil Qatar

Drilling Department



Safety Performance 2007

	LWC	Minors	Near Misses
Numbers	1	10	42

	LWCF	TRIF
Frequency	.4	4.9
2007 Targets	1.5	5.5



Safety Performance 2008

2008 End April LWC Minors Near Misses

Numbers 2 4 16

LWCF

TRIF

Frequency

2.6

7.8

2008 Targets

1.3

5.3



Lost Workday Case

Rowan Gilbert Rowe

January 3 2008



What Happened?

Injured person (A/D) was hit by Drill Collar drift, resulting in:

- Broken Thumb



Operation in progress.

Removing protector on stand of 8" Drill Collar with stuck drift.

Drift released when injured person had thumb in the protector hole.



Root Causes

- Lacking drift management



Lost Workday Case

Rowan Paris

April 30 2008



What Happened?

Injured person (A/D) got little finger trapped in snatch block resulting in:

- Partly amputated little finger



Events

- Used tugger to pull stands into finger
- Repositioning wire
- Slipped and hit tugger control
- Started rewinding trapping finger

Root Cause:

- Anchor point for snatch block too low
- Unprotected control handle





Near Miss

Rowan Gilbert Rowe

February 18 2008



What Happened?

The conductor drive hammer (14 tons) was dropped from 18 ft.


What could have happened?

Fatalities and/or serious injury to one or more people.



Immediate Cause:

Load cell system broke causing drop of load and block.





Root Cause:

Load cell system not covered by rigs preventive maintenance system



Near Miss

Rowan Paris

April 15 2008



What Happened?

A TCP gun dropped when the elevator opened after picking up from mouse hole.

Gun fell to rig floor and somersaulted out the V-door onto the cantilever deck.

What could have happened?

Fatalities and/or serious injury to one or more people.



2 7/8" lifting sub not suited for DP elevators due to wrong taper (45° instead of 18°)

Used 2 7/8" YT elevators on 2 3/8" body OD.
Elevator slips not biting.
Sub resting on top of elevator





Root Cause:

Wrong lifting equipment used.