



MAERSK OIL QATAR AS DRILLING DEPARTMENT SAFETY STATISTICS Q4 2009 – Q1 2010


Ramada Hotel

April 2010

DOIRC Meeting Q1 2010

MOQ Safety Performance

Q4 2009 – Q1 2010



MOQ Safety Performance

Safety Performance fourth quarter 2009

LWC	Minors (RWC + MTC)	Near Misses
0	0	4

Safety Performance first quarter 2010

LWC	Minors (RWC + MTC)	Near Misses
0	2	1

- Incident (what happened)

- Field engineer was using the slide hammer trying to remove the float valve from the Xceed bit box held vertically in the rig floor. The hammer slid and pinched his finger

- Reasons

- Heavy Duty Slide hammer designed to be used only when the tool was horizontal
- Fatigue

- Action to be taken

- New design (Puller to remove float values)
- Safety Alert to be sent out to the field
- Fatigue management recertification for all

